INTERIOR

BIOFA

Item no. 2090

NAPONA Basic Cleaner

1 l - 5 l



For intensive basic cleaning surfaces made of wood, linoleum, cork, tiles and natural stone.

- **Concentrate**
- **Crystal Clear Ingredient Declaration (www.biofa.de)**
- **Made with natural raw materials ****
- **Solvent-free and skin-friendly**
- **Very high biodegradability**
- **Dissolves dirt, oil and wax**

Properties:

NAPONA Basic Cleaner solvent-free is a particularly skin-friendly liquid soap made from natural raw materials. It is a basic cleaner for removing heavy soiling and old oil/wax coatings from wood and cork parquet, linoleum, tiles, natural stone, etc. NAPONA is very well biodegradable.

** Ingredients:

Water, potash-saponified coconut and soybean oil fatty acids 5-15%, lavandin oil (contains linalool).

96 per cent water and renewable raw materials
4 per cent mineral and metallic raw materials
0 per cent chemical-synthetic and fossil raw material

Processing steps:

1. Dosage The mixing ratio of NAPONA to water and the exposure time depend on the alkali sensitivity of the substrate, the type of wood, the degree of soiling and the oil/wax layer thickness. As a guide formulation, NAPONA is mixed 1:1 with water. For alkali-sensitive substrates such as oak and chestnut wood (wood discoloration due to high tannic acid content!), linoleum, etc., dilute 1 part NAPONA with at least 10 parts water.

2. processing The mixture is applied with a cloth, mop or appropriate cleaning machine. Reaction time approx. 5-20 min. (for wooden parquet as short as possible). Resoap dried areas during the application time. Depending on the degree of soiling and the thickness of the oil/wax layer, thoroughly rub or brush the surface with a cloth, brush or plate machine (with green pad). Before removing the soap solution, check on a small area whether the dirt or wax film has dissolved. This is noticeable by high foam formation when rubbing.
If the film has dissolved, remove dirt and soap residues thoroughly with clean water. Otherwise, repeat the soaping process.
Important! Carry out preliminary tests!
3. Aftecare Then clean and rinse thoroughly with clean water. However, do not flood the surface with water. After a drying time of at least 6-8 hours at room temperature (20°C/50-55% relative humidity - wood moisture must then be below 14%), it can be treated again with oil, wax or varnish. It is essential to carry out preliminary tests!
4 Cleaning of tools Immediately after use, place tools such as sanding pads, cloths, rollers, brushes, etc. in the undiluted NAPONA and allow to soak for several hours (preferably overnight). Then rinse thoroughly with clear water. Leave heavily soiled tools in undiluted NAPONA for at least 24 hours.
Do not use on equipment made of aluminum or other alkali-sensitive materials.

The information and instructions in the technical leaflet are binding. Prior consultation with the application engineering department of BIOFA is required if a deviation from these specifications is necessary. The generally accepted construction engineering practices must be observed. All previous information is null and void after the publication of this leaflet.
BIOFA Naturprodukte W. Hahn GmbH, Dobelstr. 22, D-73087 Bad Boll Germany, www.biofa-de.com, Tel. 07164-9405-0, Fax 07164-9405-96

INTERIOR

BIOFA

Item no.
2090

Recommended Equipment:




1. **009942** Flat Brush 240 mm
2. **009973** Handle for paint roller and flat brush
3. **009987** Pad green Ø 410mm for use by single disc disc machine.

Consumption/yield per coat

At a mixing ratio of 1:1, 1 liter of undiluted concentrate is sufficient for approx. 8-12 m^2 of floor area, at a mixing ratio of 1:10 for approx. 40-60 m^2.

Storage:

Store in a cool, dry and well closed place. Protect from frost.

Container:

PE/PP plastic can

Disposal:

Liquid product residues and containers that have not been emptied and cleaned must be disposed of in accordance with local/national regulations. Small residual quantities and soaked working materials can be disposed of with household waste after drying out.
Only empty and cleaned containers should be recycled.

EAK waste code according to European waste list: 20 01 30

Safety instructions:

Keep out of reach of children. In case of contact with eyes or skin, rinse thoroughly with water. Ensure good ventilation during processing and drying. Do not allow to enter soil, water or sewage system. A typical odour of the natural raw materials is possible!

Safety data sheet available on request!

GISCODE: GG 10

The information and instructions in the technical leaflet are binding. Prior consultation with the application engineering department of BIOFA is required if a deviation from these specifications is necessary. The generally accepted construction engineering practices must be observed. All previous information is null and void after the publication of this leaflet.
BIOFA Naturprodukte W. Hahn GmbH, Dobelstr. 22, D-73087 Bad Boll Germany, www.biofa-de.com, Tel. 07164-9405-0, Fax 07164-9405-96